

**Protection additionnel**

**Additional protection**



Réparation et entretien  
Janvier 2021

Repair and maintenance  
January 2021

## Protection additionnel

EXM offre une protection supplémentaire à sa série de boîtiers peints. Opter pour une couche d'apprêt époxy offrant une résistance exceptionnelle, l'enceinte non poreuse, augmentant ainsi considérablement son endurance à l'humidité.

Les propriétés de résistance à la corrosion de l'apprêt époxy en font le produit idéal protection des armoires électriques situées dans des environnements particulièrement difficiles. Il améliore la résistance de la peinture de x5<sup>1</sup>.

1. Environ.

Remarque: pour les boîtiers peints avec l'apprêt époxy supplémentaire, contactez EXM pour obtenir un devis ou utilisez [BOXCAD](#).

Canada: 1-800-363-2423

USA: 1-817-306-6166

## Additional protection

EXM offers an additional protection to its painted enclosures series. Opt for an Epoxy primer coating that provides outstanding resistance, making the enclosure non-porous, therefore drastically increasing its endurance to moisture.

The corrosion resistant properties of the Epoxy primer makes it the ideal protection for electrical enclosures located in exceptionally harsh environments. It improves the resistance of the paint by x5<sup>1</sup>.

1. Approximately.

Note: For painted enclosures with the additional Epoxy primer, contact EXM to get a quotation or use [BOXCAD](#).

Canada: 1-800-363-2423

USA: 1-817-306-6166

